

Catia lube groove macro

1. Select some planar faces of a part.
2. Click X.
3. If “Isolate → AutoKeys” is disabled. Macro waits till, user targeting sketch is isolated. (time-out 60s)
4. Done.



